




## Vehicle Inspection Request

From:

STATION HOUSE OFFICER  
RAJU HAKE  
BHANDARA(PS)  
BHANDARA  
MAHARASHTRA

To:

THE MOTOR VEHICLE INSPECTOR,  
MH36,MH02-TD-ADM\_BHANDARA  
MH-36 DY. RTO BHANDARA, NEW ADMINISTRATIVE BLDG., OPPOSITE COLLECTOR  
OFFICE, NH-6, BHANDARA - 441 904



Sir,

Subject: Regarding Vehicle inspection - / MH40BY0178-LIVO

Reference: Bhandara(PS) - - -

Subject	It is requested to inspect the above mentioned vehicle and issue the Inspection Report of Motor Vehicles involved in the below accident
Control / Crime / FIRNo	Bhandara / - -
Field Officer: Investigating officer:	<b>Field Officer:</b> RAJU HAKE, <b>Investigating officer:</b> ,
Date & Time of Occurrence of Accident	16-Sep-2023 : 02:45 PM
Case Registered Date Accident Id	16-Sep-2023 : 08:45 PM 202319376050056
Accused Vehicle	1) <b>MH40BG6986</b> , AMOL MEHAR,AT.PLOT NO 100,NR.ASHA HOSPITAL, KALPATARU COLONY, KAMPTEE, , Nagpur-441001 <b>Permenant Address in License:</b> mh3120080055765, MOHD NASIR,,NR AMBEDKAR PUTLA NEW KHALASI LINE,KAMPTEE,NAGPUR,MH,441002 <b>Current Address:</b> AT PO TA 142 VITTHAL RUKHMINI 5,,KAMPTEE,NAGPUR,MH,441002

Victim(s) Vehicle	1) <b>MH40BY0178</b> , SHRIKANT KATHALAKAR,PLOT NO. 46, GAOTHANA, PIPLA, Nagpur-440034 <b>Driver Permenant Address in License:</b> mh36/0015371/2022, Raman Tembhurkar,,, <b>Current Address:</b> civil line ward sakoli
Place of Occurrence of Accident	<b>INFRONT OF RANAT BHAWAR HOTEL</b> , Bhandara City, Bhandara Taluka, Bhandara District, Maharashtra, 441904, India
Inspecting Vehicle	<b>MH40BY0178</b> , SHRIKANT KATHALAKAR , PLOT NO. 46, GAOTHANA, PIPLA, Nagpur-440034 <b>Driver Details in License:</b> DL No : mh36/0015371/2022, Name & Address : Raman Tembhurkar S/O , , , , <b>Current Address:</b> Address : Civil line ward sakoli Contact No. :
The Damaged vehicle is placed at	Accident Spot

Inspector of Police / Sub-Inspector of  
Police  
Bhandara - Police Station  
Bhandara